9/17/09

Start Qty: 4.00

Reg'd Qty: 4.00





Setup Start Stop



Approvals: Process Plan:

Required Date: 9/18/09

QC:

Date:

Tooling:

Set Up/

Run Hours

Accept

Date: 69/69/17 SPC (Y/N):

Date: Date:

Draw

Rev.

Cust Item ID:

Customer:

Draw

Number

Plan

Code

Start Stop

Reject

Number

Run

Accept

Qty

Reject

Qty



Insp.

Stamp

Sequence ID/ Work Center ID

Start Date:

Reference:

Operation Description Revision Nbr Draw Nbr

Rev F

D3140

Waterjet FLOW CNC Waterjet FLOW WATER JET

0.00

0.00

1-Cut as per Dwg D3140 | **ENSURE THAT GRAIN DIRECTION IS CORRECT*** | Dwg Rev: Prog Rev: 2-Deburr if necessary

189-9-17

110

0.00 0.00

184-9-17

Quality Control

120

Quality Control

QC8- Inspect parts - second check

Memo

Memo

QC2- Inspect parts off machine FAI/FAIB

5) Sala 10

0.00

Work Order ID 52203

September 17, 2009 1:55:45 PM

Item ID:

D3140-91

Revision ID:

Item Name:

Doubler

Start Date:

9/17/09

Start Qty: 4.00

Required Date: 9/18/09

QC:

Req'd Qty: 4.00

Accept



Setup Start



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Run

Start



Stop

Sequence ID/ Work Center ID

130

Small Fab

Small Fab

Operation Description

Set Up/ **Run Hours**

Date:

0.00

0.00

Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Small Fab

Memo

Memo

2-Scuff surfaces with 80grit sandpaper per 1-Form as per Dwg D3140

QSI 006 3-Deburr. No sharp edges

8B09/10/07

140

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00

150

HandFinish

Hand Finishing

Chemical Conversion Coat per QS1005 4.1

Memo

0.00

0.00

Work Order ID 52203

September 17, 2009 1:55:45 PM

Item ID:

D3140-91

Revision ID:

Item Name: Doubler

Start Date:

9/17/09

Start Qty: 4.00

Required Date: 9/18/09

Req'd Qty: 4.00

Reference:

Approvals:

Process Plan:

QC:

Date:

Date:

Sequence ID/ Work Center ID

160

QC

Quality Control

Operation Description

QC3-Inspect Part Finish

Memo

170

Packaging

Identify as per dwg & Stock Location:

Memo

Packaging

QC21- Final Inspection - Work Order Release

Memo

Accept

Tooling:

0.00

0.00

0.00

SPC (Y/N):

Set Up/

Run Hours



Setup Start

Stop



Page 3

Cust Item ID:

Customer:

Draw

Number

Date:

Date:

Draw

Rev.

Run Start

Stop



Reject Insp. Number Stamp

09/10/67

Accept

Qty

Plan

Code

Reject

Qty

MF 09-10-08

180

Quality Control

0.00

0.00

- Klist Print

September 17, 2009 1:55:45 PM

Work Order ID: 52203

Parent Item:

D3140-91RevF

Parent Item Name: Doubler

Comments:

M2024T3S.032

2024-T3 .032 sheet

Component Item ID/ Item Name

Replacement Item ID

Mfg/ Purch

Purchased

Start Date: 9/17/09

Start Qty: 4.00

Remaining Qty Qty To Pick Issued

139-9-17

Status

Required Date: 9/18/09

Required Qty: 4.00

Date

Issued

Bin Primary Item Location No

Last Location

Seq ID 100

Route

Hand sf 96.7095

Qty on

Unit of

Measure

0.6211

.9316

Warehouse Loc Qty Loc Code Location 96.70953158 1.5 5

Main Warehouse MAT 102942 105555 106272 5.3 108595 3 109240 7.02 110778 23.9106316 111699 47.9789 18147 3 Page 1

AEROSPACE LTD	Work Order: 533-05	_
DART AEROSPACE LTD	5200.9	1
Description: Doubles	Part Number: D3140-9	
Description:	Page 1 o	of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article	Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
	4 ,030	,403	*			
,40	#- ,030 #30	745	7			
	4020	4.055	*			
4.00	7- 03)	5.005	*			
5,00	1- 050		1			
04			1			
		-				
			1			
		-		+		8
V V				+		
	1-6	-	+	1		
	-	1677/	-	-	1	
			+		+	
			_			
				-		
					-	
		-				

	D	Audited by:	Prototype Approval:	N/A
Measured by:	easured by:	Date: 07/09/18	Date: N/	
Date:	9-9-17	Date: 10/10/1/8		A

			Revised by	Approved
Rev	Date	Change	KJ/JLM	
. Δ		New Issue		

